


Fig. 1



7



Tom Jackson scheduled work orders

scheduled work orders
 Not in a service visit. Please start your
 service visit by entering any charge
 information and pressing the next button.

Verisae Roles - Master Filter Factor Groups, Factors, Values & Defaults

Factor Group = A grouping of fields that are related in concept and can have one or more Factors. Factor = A Field that we allow the user to assign a value to that will be used in filtering the information displayed in the Work Space.

Value = One of the acceptable values for any given field. Used as the value in query for the Master Filter

+ Geog	Factor Groups & Factors	Value Type	Default / Possible	Edit Yes/No/Down
· Ceog	Country	Possible Values	Blank / Show All	*
	State/Province	Possible Values	Blank / Show All	Yes
	City	Possible Values		Yes
	Postal Code	Possible Values	Blank / Show All	Yes
+ Organ	nizational	rossible values	Blank / Show All	Yes
	Client	Possible Values	Blank / Show All	
	Organization	Possible Values	Blank / Show All	Yes
F-100-0-100 May 24-0	Affiliate	Possible Values	Blank / Show All	Yes
	Fact Type	Possible Values	Blank / Show All	Yes
	Site	Possible Values	Blank / Show All	Yes
+ Service	ce Provider	1 cosible values	DIGIN / SIIOW AII	Yes
	SP Organization	Possible Values	Blank / Show All	Yes
	SP Site	Possible Values	Blank / Show All	Yes
	Preferred (Y/N)	Possible Values	Blank / Show All	Yes
+ Work	Order		Sidnik / Silow All	163
	Number	Possible Values	Blank / Show All	Yes
	Status	Possible Values	Blank / Show All	Yes
	Туре	Possible Values	Blank / Show All	Yes
	Date Created Range	Start Date, End Date	Blank / Show All	Yes
	Date Completed Range	Start Date, End Date	Blank / Show All	Yes
	Technician	Possible Values	Blank / Show All	Yes
	Part Number	Possible Values	Blank / Show All	Yes
	Service Action	Possible Values	Blank / Show All	Yes
	Billable Labor Range	Low Value, High Value	Blank / Show All	Yes
	Work Order Cost Range	Low Value, High Value	Blank / Show All	Yes
+ Servic				
	Number	Possible Values	Black / Show All	Yes
	Number of Trips	Possible Values	Blank / Show All	Yes
	Service Visit Cost Range	Low Value, High Value	Blank / Show All	Yes
+ Invoice	=			
	Number	Possible Values	Blank / Show All	Yes
	Status	Possible Values	Blank / Show All	Yes
	Date Created Range	Start Date, End Date	Blank / Show All	Yes
HT 190 min	Invoice Cost Range	Low Value, High Value	Blank / Show All	Yes
+ Assets				
	Asset Type	Possible Values	Blank / Show All	Yes
	Work Center	Possible Values	Blank / Show All	Yes
	In Service Date Range	Start Date, End Date	Blank / Show All	Yes
	Warranty Expiration Date Range	Start Date, End Date	Blank / Show All	Yes
	Preventative Maintenance (Y/N)	Possible Values	Blank / Show All	Yes
+ Manufa				
	Manufacturer Site	Possible Values	Blank / Show All	Yes
+ Calls				
	Call Status	Possible Values	Blank / Show All	Yes
	Action Type	Possible Values	Blank / Show All	Yes




Fig. 4a




Fig. 4b

	Situs Service &	Maintenance	Asset Types	Parvice Providers Manu	Stas Savios Validamings Asset Types Suvice Providers Manufactures Reports Messages	sebessep
Site T-0664	Outstanding Work C	Orders Approval	F All Book Ords	ns Service Calls Inve	Outstanding Work Orders Approvals All Work Orders Service Sals Inquires Pour Mark Service printed Orders	ite Pin Work Orders
Requester Temy Haughten ,	All Work Orders	Orders				
Description Lack of power, Battery appears not be	Seatup	Site Name A	West Order #	Site Name. A Work Order# Work Order Hame.	Asset Type Service Provides	Service Provider
- Church and a state of the sta	Due 01/25/2001	T-0001	12	LF Tire out of align	Dane QuicKare 4000	Western Electric
E	Due 01/27/2001	T-0024	72	Wheels locked	Dane Quickare 4000	Western Electric
General Services and the Company of	Due 01/28/2001	T-0100	62	the qk is broke	Dane Quickare 4000	Western Electric
Out of Service	Thvolced	T-0100		Remote Intermittent	Dane, Quickare 2000	Western Electric **
Asset Type	Overdue	T-0100	62	Left tire flat	Dane Quickart 2000	Western Electric
Cana Queckar 4000	Appv. Pand.	T-0100	28	Remote not working	Pane Quickar 2000	Western Electric Com
75.5	.involes d	T-0100	64	Remote not working	Dane Quickar 2000	Western Electric
AT THE REAL PROPERTY OF THE PARTY OF THE PAR	Due 02/01/2001	T-0664	74 47	Lack of power, Batt	Dane Quickars 4000	Western Electric
00039	Apply Pand,	T-0664	19	Quick Kart is Broken	Dane Quickart 4000	Western Electric
Action Total	Rejected	T-0664		Remote broken	Dana Quickare 4000	Western Electric
Order	Iny Rend.	T-0664	58	Life strut leaking h	Crown Walkle Stackr	Morrison vest
Satur	Apps. Pand.	T-0664	61	Steering wheel lose	Dane Quickart 4000	Morrison west
Ne do	Involced	T-0664	09	Rear hitch broken	Dane Quickare 4000	Western Electric
	Appu. Pend.	T-0664		Remote not working	Dane, QuicKars 4000	Western Electric
Save No Work	Appv, Pend	T-0664	99	TM It	Dane Quickart 4000	Western Electric
		Show all 17 (). Groups of 18	Groups of 18		Tree Heat 2	
	NEW Create new work order	a new work order)		
G.				53		
Verisac						




Fig. 6




Fig. 7